




Fig. 1







**Fig. 2A**  
**Prior Art**





*Fig. 2B*  
*Prior Art*



*Fig. 3A*  
*Prior Art*

	INTACT FEMUR
A	$0.221 \pm 0.057$
B	$0.875 \pm 0.119$
C	$0.698 \pm 0.122$
D	$1.217 \pm 0.150$
E	$1.315 \pm 0.131$
F	$1.208 \pm 0.131$

*Fig. 3B*  
*Prior Art*





M1-1	E1-1	$\sigma$ 1-1	PROCESS	PROCESS PARAMETERS
M1-2	E1-2	$\sigma$ 1-2	PROCESS	PROCESS PARAMETERS
$\vdots$	$\vdots$	$\vdots$	$\vdots$	$\vdots$
M1-n	E1-n	$\sigma$ 1-n	PROCESS	PROCESS PARAMETERS


700

*Fig. 5A*  
*Prior Art*

M2-1	$\sigma'$ 2-1	PROCESS	PROCESS PARAMETERS
M2-2	$\sigma'$ 2-2	PROCESS	PROCESS PARAMETERS
$\vdots$	$\vdots$	$\vdots$	$\vdots$
M2-n	$\sigma'$ 2-1	PROCESS	PROCESS PARAMETERS

701

*Fig. 5B*  
*Prior Art*







Fig. 7






Fig. 8

